

<b>Unit Price No. 1</b> <b>Concrete Sidewalk</b> <b>(per SF)</b> <b>range between</b> <b>1000SF - 1250SF</b>	<b>Unit Price No. 2</b> <b>Concrete Pavement</b> <b>(per SY)</b> <b>range between</b> <b>75SY - 100SY</b>	<b>Unit Price No. 3</b> <b>Curb Replacement</b> <b>(per LF)</b> <b>range between</b> <b>250LF - 500LF</b>	<b>Unit Price No. 4</b> <b>Asphalt Patch at</b> <b>Curb Replacement</b> <b>(per SY)</b> <b>range between</b> <b>0 - 50SY</b>
\$ 12.00	\$ 130.00	\$ 40.00	\$ 70.00
<b>Unit Price No. 5</b> <b>Full Depth Asphalt</b> <b>Pavement Repair</b> <b>(per SY)</b> <b>range between</b> <b>0-50SY</b>	<b>Unit Price No. 6</b> <b>Full Depth Asphalt</b> <b>Pavement Repair</b> <b>(per SY)</b> <b>range between</b> <b>51-100SY</b>	<b>Unit Price No. 7</b> <b>2" Mill &amp;</b> <b>2" Overlay</b> <b>(per SY)</b> <b>range between</b> <b>0-50SY</b>	<b>Unit Price No. 8</b> <b>2" Edge Mill &amp;</b> <b>Overlay</b> <b>(per SY)</b> <b>range between</b> <b>0-50SY</b>
\$ 85.00	\$ 85.00	\$ 70.00	\$ 70.00
<b>Unit Price No. 9</b> <b>2" Overlay</b> <b>(per SY)</b> <b>range between</b> <b>0-50SY</b>	<b>Unit Price No. 10</b> <b>Seal Coat</b> <b>(per SF)</b> <b>range between</b> <b>0 - 25,000SF</b>	<b>Unit Price No. 11</b> <b>Seal Coat</b> <b>(per SF)</b> <b>range between</b> <b>25,000SF - 70,000SF</b>	<b>Unit Price No. 12</b> <b>Crack Seal</b> <b>(per LF)</b> <b>range between</b> <b>0 - 3000LF</b>
\$ 70.00	\$ 0.22	\$ 0.16	\$ .65
<b>Unit Price No. 13</b> <b>Crack Seal</b> <b>(per LF)</b> <b>range between</b> <b>3000LF - 5000LF</b>	<b>Unit Price No. 14</b> <b>ADA Stall</b> <b>Symbol</b> <b>(EA)</b> <b>range 1 - 12</b>	<b>Unit Price No. 15</b> <b>Parking Lot</b> <b>Pavement Markings</b> <b>(per LF)</b>	<b>Unit Price No. 16</b> <b>Curb Striping</b> <b>(per LF)</b> <b>range between</b> <b>250LF - 500LF</b>
\$ .65	\$ 12.00	\$ .25	\$ .55

Minimum trip charge of \$2,500.00 for asphalt / concrete work.

Minimum trip charge of \$500 for pavement marking work.